






NEWS

No.09-E01
Mar, 2009

DISC PAD



NO.	APPLICATION	
<p>D2276</p> <p>(04465-37220) (04466-37120)</p>	<p>TOYOTA DYNA XZU508 Oct. '06 ~</p>  <p>X: 170.2 Y: 49.0 Z: 18.0</p>	<p>Front & Rear (AVAILABLE FROM May'09)</p>
<p>D11195M</p> <p>(58302-1GA00)</p>	<p>KIA RIO DE241/DE244 Apr. '05 ~</p>  <p>X: 93.0 Y: 36.5 Z: 14.5 X: 93.0 Y: 36.5 Z: 14.5 X: 93.0 Y: 36.5 Z: 14.5</p>	<p>Rear (AVAILABLE FROM May'09) FMSI No.D1157</p>
<p>D11201M</p> <p>(58302-2BA00) (58302-2BA20)</p>	<p>HYUNDAI SANTA FE SH81W Nov. '05 ~</p>  <p>X: 118.7 Y: 39.5 Z: 14.5 X: 118.7 Y: 39.5 Z: 14.5 X: 118.7 Y: 39.5 Z: 14.5</p>	<p>Rear (AVAILABLE FROM May'09) FMSI No.D1297</p>





NEWS

No.09-E02
Mar, 2009

BRAKE SHOE

NO.	APPLICATION									
<p>K11182 (58305-1CA10)</p> <table border="1" data-bbox="164 712 424 779"> <tr> <td>a</td> <td>b</td> <td>c</td> <td>R</td> </tr> <tr> <td>3.2</td> <td>2.0</td> <td>30</td> <td>101.5</td> </tr> </table>	a	b	c	R	3.2	2.0	30	101.5	<p>HYUNDAI GETZ Jun. '02 ~</p> 	<p>Rear (AVAILABLE FROM May'09)</p>
a	b	c	R							
3.2	2.0	30	101.5							
<p>K11192 (58350-07A00)</p> <table border="1" data-bbox="164 987 424 1048"> <tr> <td>a</td> <td>b</td> <td>c</td> <td>R</td> </tr> <tr> <td>3.2</td> <td>2.0</td> <td>29</td> <td>90</td> </tr> </table>	a	b	c	R	3.2	2.0	29	90	<p>KIA PICANTO 1.1i Jun. '04 ~</p> 	<p>Rear (AVAILABLE FROM May'09)</p>
a	b	c	R							
3.2	2.0	29	90							



MK KASHIYAMA CORP.