




# NEWS



NO.08-E01  
JAN, 2008

## DISC PAD

NO.	APPLICATION	
<b>D2270</b> ( 04465-33440 ) <b>Revised ↑</b>	TOYOTA CAMRY ACV40, 45 Jan. '06~  X: 157.7 Y: 52.1 Z: 17.0	Front (AVAILABLE FROM May'08) FMSI NO.D1293
<b>D11176</b> ( 11046948372 )	DAEWOO LANOS Sep. '99 ~ Dec. '04  X: 140.0 Y: 56.4 Z: 16.0      X: 141.5 Y: 46.5 Z: 16.0	Front (AVAILABLE FROM May'08)

## BRAKE SHOE

NO.	APPLICATION									
<b>K6741</b> ( 4600A106 ) <table border="1" data-bbox="165 1473 427 1541"> <tr> <td>a</td> <td>b</td> <td>c</td> <td>R</td> </tr> <tr> <td>3.6</td> <td>2.3</td> <td>49</td> <td>147.5</td> </tr> </table>	a	b	c	R	3.6	2.3	49	147.5	MITSUBISHI L200 KB4 Jan. '06~ 	Rear (AVAILABLE FROM May'08)
a	b	c	R							
3.6	2.3	49	147.5							



 **MK KASHIYAMA CORP.**