




NEWS



No. 10-E02
Feb, 2010

DISC PAD

NO.	APPLICATION	
D3146M (GSYD-33-28ZA) (GPYB-33-28ZD)	MAZDA ATENZA GHEFW Jan. '08 ~  X: 136.8 Y: 48.6 Z: 17.0 X: 136.8 Y: 48.6 Z: 17.0 X: 136.8 Y: 48.6 Z: 17.0	Front (AVAILABLE FROM May'10) FMSI No.D1192
D6130 (MK529989)	MITSUBISHI CANTER '07 ~  X: 123.0 Y: 52.0 Z: 17.5 X: 123.0 Y: 52.0 Z: 17.5 X: 123.0 Y: 52.0 Z: 17.5	Front (AVAILABLE FROM May'10)

BRAKE SHOE

NO.	APPLICATION									
K11195 (96226110) (PS4520005) <table border="1" data-bbox="167 1505 422 1572"> <tr> <td>a</td> <td>b</td> <td>c</td> <td>R</td> </tr> <tr> <td>4.0</td> <td>2.6</td> <td>45</td> <td>100</td> </tr> </table>	a	b	c	R	4.0	2.6	45	100	DAEWOO LANOS '99 ~ 	Rear (AVAILABLE FROM May'10)
a	b	c	R							
4.0	2.6	45	100							



 **MK KASHIYAMA CORP.**

CS Center, 1119 Otai, Saku, Nagano, 385-0009 Japan

TEL : ++81-267-65-7811 E-Mail : mki@mkg.co.jp

FAX : ++81-267-67-1833