



NEWS


No. 10-E10
Jul, 2010

DISC PAD

NO.	APPLICATION	
<p>D11227M (PW891172)</p>	<p>PROTON GEN-2 1.6i HATCH BACK Sep. '04 ~</p>  <p>X: 123.0 Y: 49.5 Z: 16.5 X: 123.0 Y: 49.5 Z: 16.5 X: 123.0 Y: 49.5 Z: 16.5</p>	<p>Front (AVAILABLE FROM Oct'10)</p>

BRAKE SHOE

NO.	APPLICATION									
<p>K2395 (04495-0K020) (04495-0K050)</p> <table border="1" data-bbox="175 1205 437 1261"> <tr> <td>a</td> <td>b</td> <td>c</td> <td>R</td> </tr> <tr> <td>4.5</td> <td>2.6</td> <td>50</td> <td>147.5</td> </tr> </table>	a	b	c	R	4.5	2.6	50	147.5	<p>TOYOTA HILUX VIGO GGN25 Aug. '04 ~</p> 	<p>Rear (AVAILABLE FROM Oct'10)</p>
a	b	c	R							
4.5	2.6	50	147.5							



 **MK KASHIYAMA CORP.**

CS Center, 1119 Otai, Saku, Nagano, 385-0009 Japan

TEL : ++81-267-65-7811 E-Mail : mki@mkg.co.jp

FAX : ++81-267-67-1833