



## SAKU, January 26, 2009 \*\* TECHNICAL INFORMATION \*\*

We would like to inform you that we change the compatibility of OE No.04495-87217-000 from K0029 to K0036.

As a result of our latest research, we found that the genuine parts have changed their shape.

From the technical point of view, we decide to change the compatible item to K0036.

If you have any question, please do not hesitate to ask us.