





# NEWS

No.09-E05  
Jun, 2009

DISC PAD

NO.	APPLICATION	
<p><b>D1276</b></p> <p>( AY040-NS132 ) ( D1060-JD00A )</p>	<p>NISSAN DUALIS J10E May. '07 ~</p>  <p>X: 142.0 Y: 50.0 Z: 16.5</p>	<p>Front (AVAILABLE FROM Sep'09) FMSI No.D1338</p>
<p><b>D11210M</b></p> <p>( 58302-3FA01 )</p>	<p>HYUNDAI SONATA '08 ~</p>  <p>X: 99.9 Y: 36.3 Z: 14.5    X: 99.9 Y: 36.3 Z: 14.5    X: 99.9 Y: 36.3 Z: 14.5</p>	<p>Rear (AVAILABLE FROM Sep'09) FMSI No.D1313</p>



 **MK KASHIYAMA CORP.**

CS Center, 1119 Otai, Saku, Nagano, 385-0009 Japan

TEL : ++81-267-65-7811    E-Mail : mki@mkg.co.jp

FAX : ++81-267-67-1833